



5/047/061

VERNAL DO/BCRA/DMRA 3809 FIELD INSPECTION FORM

Date 8/12/94 Time 10:00am Location: T5S R25E Sec. 9, Subdivision N $\frac{1}{2}$ NW $\frac{1}{4}$ SW $\frac{1}{4}$

Operator present during inspection Yes

(Names and Titles) Alan H. Chew, Claimant

Serial No. of Notice/Plan on file UTU66378 Is the operation active? Yes

Claim Name Flagstone, UMC268644

Description of operations (including access, reclamation, etc.):  
Removing rock from the northeast and southwest rim of the draw. Will progress to the southwest and northwest. Using a rubber tired front-end loader and wench truck. Hauling each piece of rock about .75 of a mile to the east on existing roads and loading same on flatbed semi-truck parked on private ground. As much topsoil as possible will be stockpiled for redistribution/reseeding later. Very difficult to estimate the amount of previous disturbance because the removal area consists primarily of highly jointed and jumbled bedrock. Probably much less than an acre. No springs, ponds, or running water in the project area. Several photographs were taken and are attached to this report.

Other Agency Permits: Will file Small Mine Application with UDOGM.

Is the operation in compliance with the Notice on file or the stipulations of approved Plan? Yes If NO describe deficiencies.

(Signature) (Print Name) (Title) (Date)

Inspector R.S. Wilson R.S. Wilson Geologist 8/12/94

Mgt. Ac-  
knowledgement Paul M. Andrews Paul M. Andrews Area Manager 8/18/94

Advise ORCA/CRS data entry specialist of inspection for data entry (Yes), Date: 8/12/94. If operation is in noncompliance, issue Notice of Noncompliance within 5 working days (N/A)

Distribution: 1 - Original to Surface Mgt. File; 1 - UDOGM (Attn Tony Gallegos)

5/047/061



Southwest side of gully looking westerly from road to the Southeast  
8/12/94 raw



Alan Chew loading large rock slab  
on to truck with wrench on pub. ground.  
8/12/94 raw